


Using the No. 902WB in the No. 902 TOP LOADER™ BAIT STATION



1. Remove Securing Screw‡ From Station.

2. Remove Cap By Twisting Counterclockwise And Lifting Cap And Bait Holder Rod From Station.

3. Remove Bait Holder Rod By Unscrewing Rod From Cap.

4. Fill Feeder Bottle With Liquid Bait And Place In Station With Drip Spout Down. Replace Cap As Shown In Illustration 5.

Align Screw Hole with Notch Before Placing Cap On.

5. Align Screw Hole With Notch Then Replace Cap By Sliding Back On To Station. Twist Cap Clockwise Into Place And Replace Securing Screw.‡

‡Securing Screw J.T. EATON Replacement Part No. 906SCREW
Optional Liquid Bait Bottle Part No. 902WB
FORM No. XINST902BOTBAF ©2017

FAMILY OWNED AND OPERATED
JT EATON™
SINCE 1932
1393 East Highland Road • Twinsburg, OH 44087
330.425.7801 • FAX 330.425.8353
www.jteaton.com

Directions for using JT EATON™ TOP LOADER™ No. 902 with the optional Liquid Feeder Bottle (No. 902WB)

1. Remove cap and unscrew bait holder rod from the cap.
2. Check inside the cap of your bottle, inside the cap will be a rubber gasket. Make sure the gasket is properly seated.
3. Fill Liquid Bait Bottle completely with liquid at room temperature (a bottle with cold liquid will take longer to create a vacuum and may drip more).
4. Once you have filled the bottle, tighten cap securely and tap the ball bearing at the sink a few times. You can also hold bottle so that tube is facing UP and squeeze the bottle until you force a small amount of liquid out, then turn over.
5. Insert filled bottle into station and secure bait station cap.

Note: All Liquid Bait Bottles **MAY** occasionally drip after a rodent drinks. Drips can also be caused by temperature changes in the station's location. Additional monitoring may be required while in use.

6. If liquid bait is no longer needed, the bait holder rod can be screwed back into the cap and the station can once again be used with JT EATON™ BAIT BLOCKS®, TOP GUN™ BAIT BLOCKS®, 2G SECOND GENERATION RODENTICIDE™ BAIT BLOCKS® or other solid block baits.

If you feel you have done all of the above and it has not helped please feel free to call JT EATON™.

FAMILY OWNED AND OPERATED
JT EATON™
SINCE 1932

800.321.3421
www.jteaton.com